


Cutting speeds




Tool speed v. Work speed

- Milling



Copyright © 2008 CustomPartNet

- Turning



Surface feet per minute

- The speed that the tool or the work moves at the point of cut.
- **SPINDLE SPEED IS NOT THE CUTTING SPEED!**
- Spindle RPM = $\text{SFM} / \text{Dia.} \times 3.82 \times \text{tooling correction factor}$

Speed chart

Cutting speed recommendations Material type	Surface feet per min (SFM)
Steel (structural)	40–60
Mild steel	90-125
Cast iron	60–80
Alloy steels	50–120
Carbon steels C1008-C1095	70–130
Free cutting steels	115–230
Stainless steels (300 & 400 series)	75–130
Copper/ Bronze	70–150
Leaded steel 12L14	275-325
Aluminum	250–350
Brass	300-750

**One hour tool life,
HSS, dry cut,
medium feed rate,
non interrupted cut,
no mill scale. For
coated carbide
cutters with coolant,
speeds may be
increased by 100-
200% - dependent
on situation.**

Example

Turn 2.000 OD 303 SS

- Experience says 120 SFM is a good choice based on our machines and tooling



- Stainless steel is generally “difficult” to machine. Tends to seize and gall.
- Requires tool with strong cutting edge


Calculated speed:

- Lathe spindle RPM

RPM = SFM/ Dia. X 3.82 x tooling correction factor.

RPM = 120 / 2.000 x 3.82 x 2 (b/c Carbide with Titanium nitride coating) = 458 RPM

- Mill Copper with .875 HSS EM
- Experience says 135 SFM is a good choice based on our machines and tooling



- Copper is ductile, being easily “pushed” by a cutting tool. High shear tooling required.
- Uncoated tools have sharper edges than coated tools

Calculated speed

- Mill spindle RPM

RPM = SFM/ Dia. X 3.82 x tooling correction factor.

$$\text{RPM} = 135/.875 \times 3.82 = 589 \text{ RPM}$$