

Brass or steel with 7/16-20 thread. This will be held in the lathe chuck. Use a 7/16-20 nut for a clamp.

This part will allow the MT1 taper in the Sherline lathe or mill to be released without using a hammer. In my mill and lathe the taper tools all exhibit a very strong hold and I do not like having to "ram" the tools out of the spindle.