


8-32 x 3/4 socket head machine screw
turn head to 0.0875 to fit holes.


Drill and tap into compound base to
match hole array. Counter bore so head
is flush or below plate.

Compound rest rotation adapter
Dimensions for 11" Powermatic/ Logan lathe

Hemm March 2017







A close-up photograph of a metal plate, likely aluminum, showing several circular holes. One hole in the center has a screw head. The surface of the plate is highly reflective and shows signs of machining, with fine lines and some discoloration. A white text box is overlaid on the image, providing instructions for the assembly.

8-32 x 3/4 socket head machine screw
turn head to 0.0875 to fit holes.
Drill and tap into compound base to
match hole array. Counter bore so head
is flush or below plate.