

Most common divisions using the 20 hole plate

Number of turns on crank

2	20
4	10
5	8
8	5
8	5
10	4
20	2
2	20
4	10
5	8
8	5
10	4
16	2 _{10/20}
20	2
25	1 _{12/20}
32	1 _{5/20}
40	1
50	1 _{6/20}
80	1 _{10/20}
100	8/20
200	4/20

Other divisions are available from the Machinery's Hand Book