



All $.261$ holes threaded 5/16-18.
 $.250$ and $.376$ holes are not threaded.
 $.250$ holes should be reamed for $.250$ steel pins.

