



The main difference between this Joint2 and Joint is the flat on the right end has been rotated 180 degrees to the opposite side along with the associated hole diameters. This is so the SHCS for clamping can face the same direction when assembled.



| |
|------------|
| ViseStopv2 |
| xy_Joint_2 |
| 03/11/2025 |
| JR |